


## **Installation Guide**


C6693M

Installation

Remove the top cover.




A 3/4" conduit is required for routing the cables with waterproof




Install the cable gland and pass cables through it.


## Mounting Dimensions




## Package Contents












Attach the included alignment sticker to a preferred position. Drill holes on the wall and install the junction box. If space behind the wall allows, you may also pass cables through the wall.




Loosen and remove the camera top cover. (Using one of the supported cameras as an example)




Make sure the rubber seal is properly installed to the center hole. The outer rim of the seal must be through and cover the





Mounting hole locations: A: IMV Series





Pass the camera's Ethernet cable through the center hole of the box and the rubber seal.




















Open a live view page on the camera's web user interface and point the camera to obtain the desired field of view.

Secure the camera lower dome.



Pelco, Inc. 625 W. Alluvial, Fresno, California 93711 United States USA & Canada Tel (800) 289-9100 Fax (800) 289-9150 International Tel +1 (559) 292-1981 Fax +1 (559) 348-1120 www.pelco.com